FAIRFIELDS-SYLVAN NEIGHBORHOOD ASSOCIATION

Indianapolis, Indiana

Sidewalk Condition Survey
Exhibit 1



LEGEND:

SCALE: 1" = 1000'
MAY 18, 2011

Walkability Survey Area

Sidewalk Condition
- Excellent
- Good
- Fair
- Poor

- Frequent Flooding
- Pending Multi-Use Side Path
- No Sidewalk Exists
- Existing Bike Lanes

Transportation Solutions LLC
CONNECTING THE DOTS
6136 N. Ewing Street, Indianapolis, IN 46220 | 317.690.9277

FISCHER DESIGN, LLC
Lebanon, IN 46052 | 317.910.8164