


FAIRFIELDS-SYLVAN NEIGHBORHOOD ASSOCIATION

Indianapolis, Indiana

Sidewalk Condition Survey Exhibit I







LEGEND:

 Walkability Survey Area

Sidewalk Condition

 Excellent
 Good
 Fair
 Poor

 Frequent Flooding
 Pending Multi-Use Side Path
 No Sidewalk Exists
 Existing Bike Lanes



SCALE: 1" = 1000'
MAY 18, 2011